

FREEVIEWSHOP

Firmware Upgrade instructions for the Globo 4100C.

Download the Upgrade.exe and the *.abs file, you will then be able to use the Upgrade program and a Null Modem Cable to update the software in the receiver.

The 10750.abs file is for 10.75GHz L.O. LNBS


The 11300.abs file is for 11.3GHz L.O. LNBS

The UNI.abs file is for Universal LNBS

You can purchase a Null Modem Cable from Freeviewshop at:

<http://www.freeviewshop.co.nz/standard-null-modem-cable-femalefemale-p-317.html>

Once you have downloaded the Upgrade.exe run the file and click Browse




Browse to the *.abs firmware update, select upgrade type to be allcode + bootloader and click next


FREEVIEWSHOP

☎ 09-8175105


🌐 www.freeviewshop.co.nz
@ sales@freeviewshop.co.nz




You will then see the serial port status being tested



Once the connection to the receiver is established the loader will check to see the firmware is correct and start downloading the firmware.



Once the download is complete the flashing of the firmware will start, the process can not be interrupted after this step.



Once the process is finished you will be returned to the following dialog box.

